Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number Database(s) EPA ID Number

HS1122 1110 AVENUE "V" NY Spills S102147105 NE 1110 AVENUE "V" N/A

> 1 BROOKLYN, NY

1.466 mi.

7741 ft. Site 2 of 2 in cluster HS

 Relative:
 SPILLS:

 Higher
 Name:
 1110 AVENUE "V"

 Actual:
 Address:
 1110 AVENUE "V"

 14 ft.
 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 9308116 / 1993-10-18

Facility ID: 9308116 Facility Type: ER DER Facility ID: 235766 Site ID: 291151 DEC Region: 2 Spill Cause: Unknown Spill Class: C3 2401 SWIS: Spill Date: 1993-09-30 Investigator: **SJMILLER** Referred To: Not reported Reported to Dept: 1993-10-04 CID: Not reported Water Affected: Not reported Spill Source: Unknown

Spill Notifier: Affected Persons
Cleanup Ceased: 1993-10-18
Cleanup Meets Std: True
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 1993-10-04
Spill Record Last Update: 1993-10-18
Spiller Name: Not reported

Spiller Company: POSSIBLE NEXT DOOR
Spiller Address: GAS STATION SUNOCO

Spiller Company: 001

Contact Name: Not reported

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was

MILLER 10/18/93: GES INSTALLED ONE ADDITIONAL VAPOR POINT/ MONITORING WELL. CROSS REFERENCE TO SPILL NUMBER 8709423 FOR 2489 CONEY ISLAND

AVE. '

Remarks: "~10 MONTHS AGO SPILL AT GAS STA.NEXT DOOR - WOULD LIKE CALL BACK -

CALLED 10/04/93 250PM TO RUTH CAR - SMELL IN BASEMENT AND WHILE

HOUSE. MS CARR SHE WILL STAR IN HOTEL AND HAS BEEN IN HOTEL BECAUSE ${\sf F}"$

Not reported

All Materials:

Site ID: 291151 Operable Unit ID: 989644 Operable Unit: 01 Material ID: 394356 Material Code: 0009 Material Name: gasoline Case No .: Not reported Material FA: Petroleum Quantity: .00

Units: Not reported

Map ID		MAP FINDINGS		
Direction		Ч		
Distance				EDR ID Number
Elevation	Site		Database(s)	EPA ID Number

Recovered: .00

Oxygenate: Not reported